



Perrottet & Piller AG

Bleikenweg 2
3178 Bösingen
Tel. 031 747 85 44
office@perrottet-piller.ch
www.perrottet-piller.ch

Referenzliste mit ausgeführten Golf-Bewässerungsanlagen

Golfclub	Meggen	9 Loch
Golfclub	Interlaken	18 Loch
Golfclub	Wallenried	18 Loch
Golfclub	Sempachersee	36 Loch
Golfclub	Gstaad	18 Loch
Golfclub	Pont-la-Ville	18 Loch
Golfclub	Les Bois	18 Loch
Golfclub	Ascona	18 Loch
Golfclub	Thunersee	9 Loch
Golfclub	Lavaux	18 Loch
Golfclub	Limpachtal	18 Loch
Golfclub	Aaretal	9 Loch
Golfclub	Vuissens	18 Loch
Golfclub	Kyburg	18 Loch
Golfclub	Schinznach	9 Loch
Golfclub	Breitenloo	18 Loch
Golfclub	Dolder	9 Loch
Golfclub	Montreux	18 Loch
Golfclub	Migros Oberkirch	27 Loch
Golfclub	Migros Waldkirch	9 Loch
Golfclub	Migros Signal de Bougy	18 Loch
Golfpark	Migros Otelfingen	9 Loch
Golfclub	Gams	18 Loch
Golfclub	Hittnau	18 Loch
Golfclub	Blumisberg	18 Loch
Golfclub	Dietschiberg Luzern	18 Loch
Golfclub	Lenzerheide	18 Loch
Golfclub	Emmental	18 Loch